

Circumference Measurement



To ensure a proper fit, circumference measurements should be taken directly on the skin with the leg straightened, using a soft tape measure. (If a soft tape measure is not available, a piece of string or yarn may be used, then measured against a hard tape measure.)



1. Locate the middle of the kneecap and measure around the leg.

Circumference Measurement Sizing Chart

(in)	13"-13 7/8"	14"-14 7/8"	15"-15 7/8"	16"-16 7/8"
(cm)	33.02-35.24	35.56-37.78	38.1-40.32	40.64-42.86
	SM	MED	LG	XL
